

UNITED STATES OF AMERICA  
DEPARTMENT OF TRANSPORTATION  
FEDERAL AVIATION ADMINISTRATION

# Air Agency Certificate

*Number* VIJR367K

*This certificate is issued to*

TurbineAero, Inc.  
d/b/a TurbineAero Repair

*whose business address is*

50 SOUTH 56TH STREET  
CHANDLER, ARIZONA 85226-3350

*upon finding that its organization complies in all respects  
with the requirements of the Federal Aviation Regulations  
relating to the establishment of an Air Agency, and is  
empowered to operate an approved* REPAIR STATION

*with the following ratings:*


ACCESSORY (05-29-98)  
LIMITED AIRFRAME  
LIMITED SPECIALIZED SERVICE (06-24-97)

*This certificate, unless canceled, suspended, or revoked,  
shall continue in effect* INDEFINITELY

*Date issued:*

06/13/1989

*By direction of the Administrator*

  
KENNETH J. REILLY  
MANAGER, AWP-FSDO-WP07

This Certificate is not Transferable, AND ANY MAJOR CHANGE IN THE BASIC FACILITIES, OR IN THE LOCATION THEREOF,  
SHALL BE IMMEDIATELY REPORTED TO THE APPROPRIATE REGIONAL OFFICE OF THE FEDERAL AVIATION ADMINISTRATION

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both*